

Navigation & Surveillance  
Thales Air Traffic Management U.S.  
10950 El Monte, Suite 110  
Overland Park, KS 66211  
Telephone: (1) 913-422-2600

BULLETIN NO. 415-SE-07 Rev. A


DATE: February 28, 2014

APPLICABLE TO: 415SE DME (098739-0001)

**SUBJECT:** This service bulletin is for wiring information if an optic coupler needs replaced. There are no defects with the existing optic coupler. Thales has found the optical coupler part # 046C05-0002 is now obsolete. It has been replaced with Thales part # 046C05-0005. The optical coupler is used to slave the 415 SE DME to the ILS ident.

**EQUIPMENT AFFECTED:**  
098739-0001 415 SE DME


**ISSUE:** There is a difference between the labeling on the two optical couplers. This may be confusing on how to wire the replacement coupler. The two drawings below show both dash number optical couplers and how to connect the wiring.



**If you have any question, please contact:**  
**Thales Customer Service**  
**Tech Support**  
**(1) 913.244.2684**

**For a complete listing of all Service Bulletin**  
**Please visit our web site at: [Thalesdsi.com](http://Thalesdsi.com)**  
**Customer support, ATM Service Bulletins**

Wiring connection for obsolete 046C05-0002 optic coupler



Wiring connection for new 046C05-0005 optic coupler

